

M3 UAX Steering Linkage Service Notice:

Due to an error at the factory, the steering linkage was made too short. In order to correct the problem attach the 20mm extension to the front end of the rod.

If you have any questions please contact either:

Bill Tannen 800-666-5000 x218

Mike Wall 800-666-5000 x507


Gary Mendenhall 800-666-5000 x298

M-3 UAX steering rod service issue

date: 2008/09/19



Steering rod extension.



Steering rod extension.