


date: 2008/07/10

Some Upper strut brackets on ALLOY seat backs were bent in the manufacturing process and are less than 24.5mm causing some strut assembling difficultly.



Bending the bracket as shown below will solve the problem.

